

BEST HOME INSPECTION, INC.

433 Union Street, Rockland, MA 02370 • Tel: 781-351-1571 Email: fred@besthi.net • www.besthi.net

Property Address					
*		t Time	Finish Time	Date of Inst	pection
Customer Name:					
Weather Conditions: Current Day	or orbital and Paris		Current Temp	o	
Services Provided:	Amount:				
Inspection Type	•••				
Wood Destroying Insect Inspection	•••	·			
Radon Test		Device #'s	WANTED THE TOTAL		
Water Quality		ž	(6)		
Other					
Total Amount Due:	,				
Note: Some items reported on or information p Regulations or (266 CMR Board of Registration	provided is a prof on of Home Insp	fessional courte ectors)	sy and is not inclu	ded under Com	nonwealth of Massachusetts
<u>Clients Responsibilities:</u> Request answers to and may NOT be readily observable by inspecti		5 questions from	the Seller/Proper	ty Owner for the	y are relevant to the purchase
1) Has a sump pump ever been installed or util	ized in the Basen	nent/Under the l	loor or Crawl Spa	ace?	
2) Do you use any type of dehumidification in	any part of the d	lwelling?			
3) Are you aware of any mold and/or air quality i	ssues in the dwell	ing?		F 70 CENC	
4) Are the Seller/Seller's Representative aware	of any structural	, mechanical, el	ectrical or materia	l defects that may	y exist on the property?
5) Has there ever been a fire in the dwelling?					
6) If so, when?					
7) What sections of property where involved?					
8) What chemical cleaners, if any, were used for	the cleanup?				
9) Has there ever been a hazardous waste spill or	n the property?		· ····································		
10) Any history of water penetration in the base	ment and/or craw	l space? Yes / I	No -If Yes, please	describe	
		1 F 1111W			
11) Does the dwelling utilize Public or Private s	sewage systems? l	Public/Private –	If Private, Date of	last maintenance	?
What was the name of the company who pe	erformed the mair	ntenance?			
12) Has the dwelling ever been tested for rador	n gas? Yes / No	o – If Yes, Can	you receive a cop	y of the report?	Yes / No
13) Has the dwelling ever been inspected for in	nsect infestation?	Yes / No -I	Yes, can you rece	eive a copy of the	report? Yes / No
14) Has a home inspector ever inspected the dv	welling previousl	y? Yes / No	- If Yes, can you r	receive a copy of	the report? Yes / No
15) Are there or has there ever been any under Provider prior to completing the transaction		anks on the prop	erty? Yes / No	- If Yes, Inform	your home owners Insurance
**Best Home Inspection, Inc. Strongly recomm qualified specialist(s) and act upon any comme					result of this inspection with
I, the undersigned, acknowledge the receipt	of the following	documents:			
An Agreement Page General Infor	rmation Page	Best Home	nspection, Inc. R	leport	
Best Home Inspection, Inc. Insect Discl	osure Page	State Required	Questions (1) - (15)	
Wood Destroying Insect Report Form N	PMA-3326	66 CMR Definit	ions and Standar	ds of Practice	Energy Audit Document
Client Signature:		_Print Name:			Date:



Rating System

- A Highest attainable rating which indicates item is functioning as originally intended.
- **B** This item is functioning less than originally intended, maintenance, repair, or upgrade is advised.
- C Caution is advised with this item as it has reached full life expectancy or is not functioning as intended. Replacement or further consultation with contractor is suggested.
- **NA** Not applicable. This item does not apply to this inspection. No rating is needed.
- NAC Not accessible. Not inspected at time of inspection. No rating is needed.

EXTERIOR	Α	В	С	NA	NAC	
1. Roof						Roofing viewed by: ☐ binoculars ☐ walked on ☐ ladder
Surface type						Age of roof - Average life of a roof is 20-25 years so you know where you stand
Exterior Chimney: See Comment E						
(liner not included)						
type					B	
Exterior Siding: type						
4. Exterior Trim: type	-					
5. Exposed gutters and down spouts						
type						
Yard drainage and landscape			/			
7. Basement/Crawl space entry						
Bulkhead/Walkout door/Other			A		e e	
8. Window wells						
9. Exterior faucet						
10. Electric service entry						
overhead / underground						
cable / encased in conduit						
11. Exterior outlets						
12. Exterior lighting						
13. Walkway						
14. Driveway						
15. Attached decks/porches/stairs						
Front type						
Rear type						
Side type						
16. Patios						
17. Retaining walls						

MAINTENANCE SUGGESTIONS AND COMMENTS:

A. Manufacturers of asphalt shingles, on the average, provide a twenty year warranty. This should not be confused with the actual roof life, which is affected by many variables. B. It is advised that reserves be set aside for repairs or eventual replacement. It is suggested that no more than two layers of roofing lie on the roof. C. All flashings should be inspected and repaired when needed annually. D. To prevent water damage to roof, sheathing, walls, ceilings and structural members, gutters and downspouts must be kept clean and clear and free of debris. It is suggested that you check periodically to ensure all is working well. E. Local regulations in some communities require the presence of a flue liner when using certain fuels. Consult your local authorities. F. Window wells should be cleaned annually. G. Exterior faucets should be drained during the colder months to prevent freezing. H. Driveway should be sealed annually to extend its life. I. The underside of decks and porches not accessible at the time of this inspection should be made accessible to check for damage or rot or infestation.

Note: Detached or outpost buildings such as garages, sheds, barns ect. And recreational items such as pools, hot tubs, courts, rinks ect. are not included - See 266 CMR.

GARAGE type	Α	В	С	NA	NAC	
1. Foundation: type						
2. Floor: type	*****					
3. Wall: type						
4. Windows						
5. Doors (operation)						
6. Safety components						
7. Doors						
□ locks □ penels □ rollers						
☐ springs ☐ windows ☐ track		35				
8. Fume barrier						
9. Fire door						
10. Fire grade sheetrock						
11. Roof: surface						
12. Siding: type						
13. Trim: type						
BASEMENT and/or CRAWL SPACE AREAS						
1. Foundation: type						
2. Basement / Crawl space floor system:						
type		,				
3. Basement Windows	-					
4. Load bearing girders/Headers:						
type						
5. Support columns: type						
6. Sill		6.576				
7. Subfloor						
8. Floor joists						
9. Interior chimney: type						
(Liner not included)						
10. Insulation						
11. Water Penetration and dampness						
See Notes F and H	spec	tion]] E	vide	nce noted at time of inspection (see comment 8)
☐ Water stains: location		_				escence: location
Sump pump present : Yes No NAC Recommen	nded] Ye	es [□N	0

A. Fume barrier, fire grade sheetrock, and fire doors are required in most new construction. For safety if your attached garage does not have these features you should consider adding them. B. Minor cracks in basement walls and floors represent normal shrinkage. To reduce possibility of any water penetration they can be filled with hydraulic cement. C. Cracks that are offset or "V" shaped are signs of settlement. These cracks less than 3/16" should be monitored and if movement is observed immediate attention will be required. D. Examination of structural members, walls, floors, ceilings, wiring, piping, etc., cannot be conducted. These areas are partially finished rendering these items inaccessible. E. Lumber, trees and adjustable columns are subject to shrinkage and deterioration, while they are acceptable under most circumstances, cement filled steel lally columns are preferable. F. Efflorescence is the white powdery substance often evident on concrete walls and floors. It is usually an indication that dampness or water penetration has occurred at some time.

G. It has been noted that proper ventilation should be maintained to minimize deterioration caused by a variety of sources. H. This report has noted some evidence of water penetration. The source and amount cannot always be determined at the time of inspection. Consult current owner for a historical perspective if possible. I. Check pump's ability to function at least once every month. Further, unless water is in sump well or easily obtained, complete sump action will not be able to be ascertained by inspector during this inspection.

CENTRAL HEATING AND COOLING	Α	В	С	NA	NAC	□ Oil	☐ Natural Gas	□ Electric	□ Propane
Thermostats: Location									Man Man A 1994
2. Asbestos observed: Location									
3. Fire grade sheetrock							* 1:		
4. Emergency shut off: Location									
5. Exposed flue and damper from the heat plant / intake and									
exhaust									
6. Any thimbles? ☐ Yes ☐ No								2000	
7. Boiler: type									
□ PSI □ temp									
☐ sight glass ☐ low water cut-off									
□ exp. tank □ press. relief valve									
□ auto feed									
8. Burner/Gun									
9. Circulator pump				7					
10. Zone valve		1							
11. Pipes: Copper / Black Iron / Plastic / Other								i arress	
12. Furnace: type								N	IOTE: Best Home Inspection
13. Circulator fan								s ti	uggests on any <i>Heating Systems</i> hat a service man check for any
14. Filter								C	racked heat exchanger.
15. Duct work:									
Aluminum / Fiberglass / Steel / Other									
16. Electric									
17. Space Heaters: Location									
18. Fuel Tank ☐ propane ☐ oil					И				
☐ fill & vent stacks ☐ emergency cut offs									
19. Cooling system		145							
20. Compressor									
21. Evaporator unit									
22. Service line insulation sight glass									
23. Condenser drain									
24. Duct work A/C only									
Aluminum / Fiberglass / Steel / Other									
25. Temperature ☐ A/C cycle ☐ Heat cycle									
26. Electric disconnect							THE RESERVE THE PROPERTY OF TH		
27. Compressor slab									

A. We suggest that you obtain a major service policy from a dealer or contractor which should include annual servicing, adjustments, efficiency testing, warranty and emergency service. B. In the event that the unit is a coal conversion furnace/boiler, it is at the end of its economic usefulness. Expect repairs or replacement. C. To determine the condition of the heat exchanger in Heating units, major disassembly by a heating technician is required. This report does not represent the condition of the heat exchanger and we recommend that you have this evaluated at your earliest convenience by a licensed technician. D. Relief valves, valves, gauges, switches, and other safety devices cannot be tested. They are listed on the report to denote that they were observed in place of the system. E. Asbestos should be properly encapsulated or removed professionally. F. All material must be kept clear of contact with electric baseboard for safety. Thermostats have a limited life expectancy. G. Presence of a radiator, baseboard or diffuser does not represent a functioning heat source or sufficient heating or properly connected to heating system. Conusit with heating technician. Radiant heat in slabs and ceilings is not accessible. H. Air conditioning units and heat pumps cannot be operated out of season as this could cause damage. Depending on the system, the usual cut off temperature is 60°F. I. Most compressors, condensers and evaporators are sealed units, therefore not accessible. J. Annual servicing of the A/C heat pump system by a licensed technician is advised.

ELECTRICAL SYSTEM	Α	В	С	NA	NAC	
Accessible wiring						
☐ copper ☐ romex ☐ knob & tube						
☐ aluminum ☐ BX ☐ ALCU compatible						
Service panel box						
Main disconnectAMP						
Breaker/Fuse 15GFCI						
20AFCI				á		
30 40 50 60 100						
Supply □ 120V □ 120V/240V						
Service panel box location						
Sub panel location						
Panel readily accessible ☐ Yes ☐ No						
Main service wire type to conductors						
☐ CU/A1 ☐ Anti-oxidant ☐ Copper		4				
Panel ☐ Breaker ☐ Fuse						
Ground terminal bars bounded to panel						
☐ Yes ☐ No						
Termination compound used						
☐ Yes ☐ No						
3. Electrical grounding/bonding						
☐ Within 5' of water main						
☐ Both sides of water main						
☐ Grounding rod						
☐ Water pipe						
☐ Ground not accessible						
Over current devices in on position						
□Yes □ No						
Number of dedicated circuits			e:			
6. Junction box/Plate covers						
7. Electrical additional comments:						
See comment C for Smoke/Fire detectors			<u> </u>			
3 33 33 33 33 33 33 33 33 33 33 33 33 3				ļ	ļ	
					<u> </u>	
	1		-	1		

A. The decision to upgrade can be influenced by client need, local regulations and mortgage lending institutions. B. Where aluminum wiring is present, switches and outlets should be checked periodically. C. Smoke detectors should be installed and approved by the local fire department prior to purchase. Best Home Inspection makes no representation as to the operability or installation of smoke detectors. D. Once or twice a year flip circuit breakers off and on to maintain good mechanical contact. GFCI breakers or outlets should be tested monthly. E. Ground Fault interrupter outlets or circuits are advised wherever electrical may come into contact with water.

PLUMBING SYSTEM	A	В	С	NA	NAC	
Supply □ Well □ Municipal □ Other						
Waste ☐ Septic ☐ Town ☐ Other						
See note "E" Water pressure						
1. Water main/Meter						
☐ galvanized ☐ brass						
□ copper □ lead						
□ CPVC/PVC						
Location of water meter/main shutoff						
2. Visual condition of accessible feed lines and connectors						
□ copper □ lead □ brass						
☐ galvanized ☐ CPVC/PVC						
3. Visual condition of accessible waste lines and connectors						
□ brass □ copper □ cast iron						
☐ galvanized ☐ lead ☐ CPVC/PVC						
□ other						
4. Main vent stack						
5. Accessible well equipment						
6. Laundry tub						
7. Washer/dryer connections (operation not tested)						
8. Water heater: type						
Make						
Gallon capacity						
Vacuum / temperature / pressure relief valves						
Manufacturing date/Approx age						
Specialty items: Jacuzzi tubs, steam shower, sauna etc.	0.400000000000		1726 140			
10. Sewer ejector pump						
*)				
				<u> </u>		
	<u> </u>			<u> </u>	ļ	
				<u> </u>		
	1				1	

A. Manufacturers' warranties for hot water heaters vary from manufacturer to manufacturer; this should not be confused with actual life expectancy which could be more or less. Please refer to the warranty for terms if any. B. The type of sewage disposal system as noted above is determined by information provided by seller, broker or client. It is not a determination of its actual type, design or condition. An optional inspection report is available (not provided by Best Home Inspection) to offer an opinion of the system's type, effectiveness and condition. C. No conclusions as to quality and quantity of the water supply are implied. It is recommended that you have both the quality and quantity test performed. D. Depending on your individual needs, a tankless unit may not provide you with sufficient hot water. To increase quantity you may wish to consider a booster tank or separate water heater. E. Main water shut offs, individual fixtures shut offs, and other valves are not tested. F. Follow manufacturer's recommendations for all water conditioning equipment. Failure to provide adequate maintenance can lead to equipment malfunction and effect water quality.

INTERIOR	Α	В	С	NA	NAC	
1. Door: main						
rear						
side						
other						
2. Sliding doors						
3. Fireplace: ☐ fire box ☐ smoke shelf ☐ dampers ☐ hearth						
Stairways and handrails						
5. Halls						
6. Skylights: locations of						
Number of skylights:		e?				
7. Whole house fan						
8. Wood stove (UL label):						
☐ hearth ☐ stove ☐ fire wall ☐ smoke pipe						
Bathroom type and/or location:			1			
sink/faucet/toilet				7		
tub/shower/shower walls		7	7			
outlet						
Flooring: type	7	7				
Other walls: type						
Heat source: Baseboard / radiator / diffuser / other						
Exhaust fan / ventilation						
10. Bathroom type and/or location:						
sink/faucet/to:let						
tub / shower / shower walls						
outlet						
Flooring: type						
Other walls: type						
Heat source: Baseboard / radiator / diffuser / other						
Exhaust fan / ventilation				-		
11. Bathroom type and/or location:						
sink/faucet / to let						
tub / shower / shower walls						
outlet						
Flooring: type						
Other walls: type						
Heat source: Baseboard / radiator / diffuser / other						
Exhaust fan / ventilation						

A. Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement. B. Wood/Coal stoves are inspected visually only, fires are not started due to the prohibitive amount of time required. If applicable, obtain a permit from the local building inspector or fire marshal before operating any solid fuel stoves. C. Check with current owner for location and condition of any and all screens and storm windows. D. No representation is made for the ability of insulated windows or skylights to be insulated. Broken thermal seals may not be detected at this inspection, due to the nature of the deficiency. E. We recommend all structures built prior to 1978 be tested for lead paint and other hazardous materials. F. Cracks in grouting of ceramic tile joints are commonly due to normal shrinkage. Re-grouting of these cracks is a maintenance responsibility of the home owner during the life of the home. Lack of maintenance will cause water penetration, lifting of tiles and deterioration of flooring, plaster, drywall and structural members around tubs and showers. Plaster or sheetrock behind tile is not accessible.



INTERIOR	Α	В	С	NA	NAC	Occupied conditions and stored items making areas and items not accessible: Yes / No
Room: Kitchen						
Overall condition of cabinets & counter tops						
2. Sinks						
3. Appliances						
☐ Stove						
Ovens						
☐ Cooktop						
☐ Microwave						
☐ Dishwasher						
☐ Refrigerator						
☐ Compactor						
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Doors						
Electric outlets						
Heat source: Baseboard / radiator / diffusers / other		/				
Room:						
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Doors						
Electric outlets						
Heat source: Baseboard / radiator / diffusers / other						
Room:						
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Doors						
Electric outlets						
Heat source: Baseboard / radiator / diffusers / other						
				1	1	

INTERIOR	Α	В	С	NA	NAC	Occupied conditions and stored items making areas and items not accessible: Yes / No
Room:						
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Door						
Electric outlets						***************************************
Heat source: Baseboard / radiator / diffusers / other						
Room:					120	
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Door						
Electric outlets						
Heat source: Baseboard / radiator / diffusers / other						
Room:						
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Door			45/43.	2000000000		
Electric outlets						
Heat source: Baseboard / radiator / diffusers / other						
Room:						
Ceiling: Type						
Windows						
Walls: Type						
Flooring: Type						
Door	1					
Electric outlets						
Heat source: Baseboard / radiator / diffusers / other						
	78					



ATTIC SPACE	A	В	С	NA	NAC	How observed:
Access to attic						
□ scuttle □ stairs						01.1.2.4.4.0.0.3.0.4.4.4.4.4.4.4.4.4.4.4.4.4.4
□ pull down □ none						
Structural supports						
☐ truss ☐ rafter						
post & bean collar tie						
Roof backings						
☐ wood planks						,
□ plywood			ā			The state of the s
4. Ceiling joist						
5. Flashing	T	0				Anna Anna and Anna an
□ vent pipes □ valleys					21	
☐ chimneys ☐ drip edge						, , , , , , , , , , , , , , , , , , , ,
Evidence of water penetration						MARKAN MALAN MARKAN
7. Insulation (visible attic only)					a	
type						**************************************
8. Ventilation						
9. Attic flooring	7	7				
						A second representation of the second
A. The home buyer should be aware that prior to the adoption of fed						
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectory faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he foam Formaldehyde Insulation in walls cannot be determined by evidence of U.F.F.I.	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of ro and condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectouyer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he	n inv at bu	estm ildup	ent in	of in sumi	sulat	odes in the mid 70's, homes were typically built with minimum insulation. Today's home ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ura Home Inspection recommends an air quality test when the inspector locates visually test when the inspector locat
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of ro and condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of United States in the condensation in winter.
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of ro and condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ure
MAINTENANCE SUGGESTIONS AND COMMENTS: A. The home buyer should be aware that prior to the adoption of fectoryer, faced with rising energy costs, should consider the return of sheathing and shingles. Provide maximum air flow to minimize he recommended to the comment of the co	n inv at bu	estm ildup	ent in	of in sumi	sulat	ion upgrades. B. Attic ventilation is an important factor in the life expectancy of roand condensation in winter. Do not cover or block vents. C. The presence of Ure

Date

Signature

AN AGREEMENT

What you will receive:

In exchange for the payment fee, Best Home Inspection, Inc. agrees to:

- Perform a Home Inspection in accordance with the Massachusetts "Standards of Practice" (266 CMR 6.00), which includes readily accessible installed systems and components to the home and garage (see exceptions below), and submit a confidential written report prepared exclusively for you.
- Perform a separate Termite/Wood Boring insect inspection and provide Form NPMA-33 (FHA/VA mortgage approved).

Our Mission: To provide you, the "Client" with a better understanding of the property conditions and basic operation of its primary components as observed at the time of the inspection.

Limitations: The Inspection and the notations in your Report are on a visual and where visible basis only. Best Home Inspection, Inc. does not inspect any item which is not observable or readily accessible at the time of the inspection. and does not: move or climb over furniture/storage/appliances/personal items of any kind, lift ceiling tiles, remove wallpaper/siding/insulation/floor coverings, probe into or dismantle any component, move mulch/soil, or see through walls. Your Inspector will not inspect any area, attic crawlspace, or component(s) where access is: obstructed, wet, unsafe, insufficiently lighted, any dimension of the opening or interior is less than 30 inches, that requires removal of fasteners or paint, where entry may damage the property, or where any dangerous or adverse conditions are present or suspected.

Disclaimers: Best Home Inspection, Inc. and your Inspector are not an insurer or guarantor against defects, and make no guarantee or warranty, express or implied, as to the future performance, expected lifespan, fitness of use, condition, or adequacy of any inspected component, structure or system. The information provided to you represents the opinion of Best Home Inspection, Inc. only. Only those components specifically mentioned in the Report have been inspected, and those components not mentioned or not readily accessible are not part of your inspection. Best Home Inspection, Inc. makes no representation, implied or otherwise, concerning the condition of non-inspected areas or components, and assumes no responsibility for: hidden or concealed damage, latent or intermittent defects, the costs associated with repairs of any non-inspected component, or the accuracy, opinions or finding s of any other Inspector or Companies. This Inspection is not technically exhaustive and shall not be construed to be a comprehensive Architectural and/or Engineering study of the property or substitute for any insurance policy or Manufacturer's Warranty.

In the event that you believe the condition of a component has not been accurately described, it is the Client's responsibility to notify Best Home Inspection, Inc. in a timely manner and prior to any repairs, alterations, or modifications, with the exception of emergencies. Failure to notify Best Home Inspection, Inc. as stated above shall constitute waiver of any and all claims against Best Home Inspection, Inc. and your Inspector. Best Home Inspection, Inc. assumes no liability toward costs associated with repairs made prior to Best Home Inspection, Inc.'s re-inspection.

Excluded items from your Home Inspection include (but are not limited to): mold/air quality testing, radon gas testing (available by request), lead paint/asbestos testing, sewer/septic systems, wells/water conditioning systems, water quality testing (available by request), furnace heat exchangers and emergency shutoffs, electronic air filters/humidifiers, sheds/outbuildings, pools/pool equipment, CATV/CATVI/telephone/network interfaces, security/fire systems, smoke/carbon monoxide detectors, fire escapes, intercoms/radios, sprinkler/irrigation systems, fencing/trees, soil and geological conditions, central vacuum systems, window air conditioners, Instant Hot systems, sensory lighting, paint/wallpaper/finish treatments, cosmetic damage/normal wear and tear, drapes/blinds/window treatments, underground components or underground portions of components, antennas/surge suppression devices, ponds/fountains, recreational equipment, toxic or flammable gases/electromagnetic fields, storm windows/doors, screens, awnings, solar equipment, chimney flues/interiors, cesspools/drywells/floor drains, operation of automatic safety controls of any component, and any systems or components that are shut down or inactive. Best Home Inspection, Inc. does not make an assessment of compliance with current building codes, and is not responsible for determining repairs/corrections needed to satisfy current building codes or any other regulations. Best Home Inspection, Inc. does not report on whether a property may be lawfully used for rental, business or any other use, and does not research past or present building permits, or product recalls/notices. We recommend you visit www.cpsc.gov if recalls are a concern of yours. Pest Inspection: Does not include rodents/roaches/other general pests and is subject to the same limitations, disclaimers, and restrictions as described and additionally on Page 2 of Form NPMA-33.

Additional restrictions: The weather can and may affect your Inspection. Best Home Inspection, Inc. cannot simulate weather conditions other than those present during the Inspection day, and is not responsible for predicting present or future performance of any components. Your Inspector will not: shovel/traverse over or through snow/ice/bud and will not return to the site to reevaluate non-accessible components under different weather conditions (additional re-inspection fee). Central air conditioning systems and Whole House Fans are not operated between Nov. 1st and Apr. 1st or when the outside temperature has dropped below 60F at any time during the previous 24hrs, due to the possibility of system damage. Central air conditioning/furnace combos and heat pumps will be tested in one mode only, to avoid possible system damage. Kitchen appliance testing includes permanently installed appliances only and for basic power up only. Washers/dryers are not included. Operations/testing of windows and electric outlets will be limited to a representative number of each readily accessible item per room. (Typically 1-2 per room). All exterior/roofing inspection of the home and garage will be done from ground level. Your Inspector will not inspect rooms that are locked or contain sleeping persons. Best Home Inspection, Inc. reserves the right to exclude any item if occupants/tenants are present during the inspection, and inspection could disrupt such persons.

The Client signing this agreement warrants and represents to Best Home Inspection, Inc. that he/she is expressly authorized to sign this agreement by the spouse or other person/entity purchasing the property in question. If the Client is not present for the Inspection, then this agreement becomes part of the Report and acceptance of such Report and payment constitutes and acceptance of the terms in this agreement. This Agreement represents the entire agreement between the parties, and there are not other agreements either written or oral.

If you or anybody on your behalf chooses to initiate any type of civil action or law suit against Best Home Inspection, Inc. or its inspector as a result of this inspection, in which Best Home Inspection, Inc. prevails, you agree to indemnify and reimburse Best Home Inspection, Inc. for its attorney fees, costs and expenses. This inspection is for your use and benefit only it may not be assigned or relied upon by any other party without written consent from Best Home Inspection, Inc.. You also agree to indemnify and hold harmless Best Home Inspection, Inc. for any subrogation action filed by an insurance company or any other third party as a result of this inspection.

Best Home Inspection, Inc. reserves the right to retain the Inspection Report if the fee is not paid for at the time of the inspection. If the Inspector is requested to go back to the Property after the inspection to check a component that was turned off, not accessible, or rated NA, there will be a additional charge.

Now that you have read this agreement, understand it, and all of your questions have been answered, we thank you and trust that this Report will assist you in your decision making process. Best Home Inspection, Inc. is happy to provide you with any further assistance you may need regarding this report for up to 1 year from the date of your Inspection! Please sign below:

I have read, understand, and agree to all terms and conditions of this agreement, and wish to proceed.

Print Name	Inspected Property Street Address
Signature	Inspected Property City, State, Zip
Date , 20	